Stress Risers--How to handle with fatigue loading

Fully Reversed Loadings:

Find the theoretical stress concentration factor, K_t

Geometry Loading Mode

Find the notch Sensitivity, q material notch dimension

Calculate K_f

multiply σa by K_f

Plot information on Goodman Diagram as usual

Fluctuating Loadings:

Treat σa the same way as fully reversed (i.e., multiply it by Kf)

If the material is $\textit{brittle:}\ multiply\ \sigma m_{nom}$ by the full value of Kt

If the material is **ductile**:

now call Kf -- Kfm

$$if K_{f} |\mathbf{s}_{\max_{nom}}| < S_{y} \qquad K_{fm} = K_{f}$$
$$if K_{f} |\mathbf{s}_{\max_{nom}}| > S_{y} \qquad K_{fm} = \frac{S_{y} - K_{f} \mathbf{s}_{\alpha_{nom}}}{|\mathbf{s}_{m_{nom}}|}$$
$$if K_{f} |\mathbf{s}_{\max_{nom}} - \mathbf{s}_{\min_{nom}}| < S_{y} \qquad K_{fm} = 0$$

Given the following information, determine the factors of safety for the machine component given below:

D = 1.125 inches d = 1.0 inches b = 2.00 inches l = 6.0 inches r = 0.5 inches a = 5.00 inches

$$\label{eq:Fmax} \begin{split} F_{max} &= 1100 \text{ Ib} \\ F_{min} &= 100 \text{ Ib}. \end{split}$$

Material is SAE 1040 normalized steel-- S_{ut} = 80 kpsi, S_y = 60 kpsi Surface is machined. Reliability = 99.9%