
Preamble TX
Start Symbol TX
Timing Bits TX
Phase Shift
Ack RX
Strength Pulse TX
Sender
Mac Delay
Packet Transmission
Receiver
Packet Reception
Preamble RX
Start Symbol RX
GetTiming
Strength Pulse RX
Ack TX
Time
0
1
2
3
4
5
6
7
8
9
10
11
12
13
x 10^4 clock ticks (on a 4MHz clock)