

Review - Exam II

Static Failure Theories

Ductile Materials

Brittle Materials

Fatigue Analysis

S - N Diagrams

$$S_f = aN^b$$

Marin Factors

Stress concentration factors

Notch sensitivity

Fully Reversed

Fluctuating

Goodman Failure Line

Mean Stress

Alternating Stress

Load Line

