In class assignment 4- Stress

This assignment will reinforce what we have discussed about stresses and combined loadings.

F = 300 lb.

Draw free body diagrams for all components.

Compute the maxima of the torsional stress and the bending stress in the arm BC and indicate where these act

Locate stress elements on the surface of shaft A and calculate all stress components.

